DYNAMARINE

2 Arkadias & 125 Dim. Gounari Str. Glyfada 16561, Athens, GR Tel: (+30) 210 9628379 (+30) 210 8941667

Email: info@dynamarine.com www.dynamarine.com

DYNAMARINe SERVICES Shipboard Incident Investigations

Scope of service: This service is provided based on IMO MSC-MEPC.3/Circ.3 for marine incidents and by implementing appropriate maritime industry guidelines and techniques for identifying root cause and actions to eliminate causes. Such actions can be short, medium and long-term as well as introducing changes to the system when deemed necessary for preventing recurrence and continual improvement related best practices

Criteria: This service is provided on board in conformance with OCIMF TMSA 3 as follows:

- On scene inspection for identifying the extent of the damage
- Review of records and evidence
- Review of data from on-board available equipment
- Statements from crew members and witnesses
- Identification of human factors contributing to the incident
- Assessing the extent of regulatory and procedural compliance
- Review of vessel's operational activities and priorities
- Review of communications and reports with external organizations involved in the process
- Review process of the collected data and information
- Reporting conclusions determining contributory and root causes

Outcome: Following completion of the process a detailed report is issued with recommendations for actions required to eliminate root cause and other significant human element factors which have contributed to the incident













